




UK Recall Notice

Safety Recalls for the United Kingdom available on the Web

Connect-it 2000W Fan Heaters



Models Affected: ES140 & ES127

It has come to Their attention that for a very small number of heaters, a fault in the mains plug of the heaters may lead to the plug overheating.

If you have one of these heaters with one of the batch numbers below, then STOP using the heater immediately.

Please call them free on the number below for details of returns process and a full refund.

They apologise for any inconvenience and assure you that no other Connect-it brand product is affected.

All heaters are batch coded in the form EP00 XXX - Your heater is only affected if in the batch code format above the xxx is replaced by the following numbers:

344,358,359,360,361,362,363,364,480.

Call us free on: **0800 328 9508**

Connect-it
41 Ramsgate Street, Salford
Greater Manchester M7 2YL

Source :- Trading Standards

1st February 2010