

Hyundai and Synergy Vacuum Cleaners - recall

The following notice has been issued by the retailer:

CUSTOMER NOTICE

IMPORTANT PRODUCT RECALL

Vacuum Cleaners

Product Codes:

PLU 256749 HYUNDAI 1200W CYCLONIC VAC

PLU 249368 SYNERGY 1200W/1400W CYCLONIC VAC



A quality problem has been identified with a small amount of the above vacuum cleaners which reportedly have been known to overheat, emitting black smoke and eventually combusting into flames. As a result they have been taken off sale and as a precaution we are recalling those already sold. If you have one of the affected vacuum cleaners, please stop using it immediately. Customers who have purchased any of these vacuum cleaners should return it immediately to any Poundstretcher store where a full refund will be given. A receipt is not necessary.

WE APOLOGISE FOR ANY INCONVENIENCE CAUSED

THIS RECALL DOES NOT AFFECT ANY OTHER PRODUCT